

UPM-3 COMPETITION POWDER MEASURE - UPM3 COMPETITION POWDER MEASURE

RCBS UPM-3 COMPETITION POWDER MEASURE The RCBS UPM-3 Competition Powder Measure combines the proven Uniflow Powder Measure with a powder baffle and Micrometer Adjustment Screw for even more precise measurements. The powder baffle controls the powder flow and the pressure of the powder column on the metering unit, while the Micrometer Adjustment Screw allows for precise adjustments to the metered charge. This also allows reloaders to record the number for future reference. The handle can be positioned on either the right or left side, depending on your preference. It's essential to note that this powder measure should be used in conjunction with an accurate powder scale for setting the original charge and checking charges occasionally during the run. Lastly, never use the Competition Powder Measure with black powder. Micrometer Adjustment Screw allows precise adjustments to the metered charge and lets reloaders record the number for future reference. **FEATURES** One Metering Cylinder and Screw for both Rifle and Pistol A single screw assembly can meter .5 to 100 grains of powder .10 grain accuracy with Micrometer for precise adjustments Quick Change Drain Attachment for quick powder drain capability Powder Baffle controls the powder flow and the pressure of the powder column on the metering unit Threaded hopper for easy removal 1 pound hopper capacity Ambidextrous design Cast iron construction Drain attachment and two drop tubes included



Attributes

- Name: UPM3 COMPETITION POWDER MEASURE
- Manufacturer: RCBS
- Product no.: 430113395
- Mfr. No.: 9032
- Accuracy: 0.1mm
- Delivery weight: 1.406kg
- Shipping height: 70mm
- Shipping width: 127mm
- Shipping length: 305mm
- UPC: 604544696738

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: UPM3 Competition Powder Measure Safety Instruction Guide](#)

UPM3 Competition Powder Measure Safety Instruction Guide

Introduction

Thank you for choosing the RCBS UPM3 Competition Powder Measure. This guide provides important safety instructions to ensure the safe use of your powder measure. Please read this guide carefully before using the product to ensure a safe and effective experience.

General Safety Guidelines

- Ensure that the powder measure is used in accordance with the manufacturer's instructions.
- Always use the powder measure in conjunction with an accurate powder scale to set the original charge and check charges during use.
- Never use the Competition Powder Measure with black powder, as it poses significant safety risks.
- Keep the powder measure out of reach of children and vulnerable individuals.
- Regularly check for any signs of wear or damage to the powder measure and discontinue use if any issues are identified.

Specific Safety Precautions for Use

- When adjusting the Micrometer Adjustment Screw, do so carefully to avoid overtightening, which may damage the mechanism.
- Ensure that the handle is securely positioned on your preferred side before use to prevent accidental disengagement.
- Always operate the powder measure in a wellventilated area to minimize inhalation of any powder particles.
- Avoid distractions while using the powder measure to maintain focus and accuracy.
- Store the powder measure in a dry place when not in use to prevent moisture damage.

Instructions for Installation and Usage

1. Installation

- Select a stable and flat surface for the installation of the powder measure.
- Secure the powder measure to the surface if necessary to prevent movement during operation.
- Attach the threaded hopper to the powder measure, ensuring a tight fit to prevent leaks.

2. Usage

- Before filling the hopper, ensure it is clean and free of any residue from previous powders.
- Fill the hopper with the desired powder type, ensuring not to exceed the 1pound capacity.
- Adjust the Micrometer Adjustment Screw to set the desired metered charge. The measure can meter from 0.5 to 100 grains of powder with a precision of 0.10 grains.
- Use the Quick Change Drain Attachment to quickly drain any excess powder when necessary.
- After measuring, always check the charge weight with an accurate powder scale to confirm accuracy.
- Record the metered charge for future reference.

Disposal Instructions

- Dispose of any unused or expired powders according to local regulations for hazardous materials.
- When disposing of the powder measure itself, check with local waste management authorities for proper

disposal methods.

- Do not dispose of the powder measure in regular household waste if it contains any residues of powder.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the UPM3 Competition Powder Measure, please contact the manufacturer directly. Ensure that you have the product information and your receipt available for reference.

By following these safety instructions, you can ensure a safe and effective experience with your RCBS UPM3 Competition Powder Measure. Thank you for your attention to safety.