

Powder Funnel for Dillon Powder Measure - Dillon Powder Measure Adapter for Frankford Arsenal X-10

Dillon Powder Measure on your FA X-10 If you are transitioning from the Dillon ecosystem, or simply prefer using a powder measure that integrates case neck expansion into a single die, this adapter is the perfect solution. With this adapter, you can now retrofit the Dillon Powder Measure onto your Frankford Arsenal X-10 press while fully retaining the original fail-safe mechanism.



Attributes

- Name: Dillon Powder Measure Adapter for Frankford Arsenal X-10
- Manufacturer: ARMANOV
- Product no.: EU2018344
- Mfr. No.: DPMAX10
- Colour: Blue
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for Powder Funnel for Dillon Powder Measure Adapter](#)

Safety Instruction Guide for Powder Funnel for Dillon Powder Measure Adapter

Introduction

Thank you for choosing the Powder Funnel for Dillon Powder Measure Adapter designed for the Frankford Arsenal X10. This guide provides important safety instructions and recommendations to ensure the safe and effective use of this product. Please read this guide carefully before using the adapter.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always follow the manufacturer's instructions for installation and usage.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of damage or wear.
- Report any unsafe conditions or accidents to the appropriate authorities.
- Stay informed about product recalls and safety updates through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always ensure that the Dillon Powder Measure is securely attached to the Frankford Arsenal X10 before use.
- Never exceed the recommended load capacity of the Dillon Powder Measure.
- Use appropriate personal protective equipment, such as safety glasses and gloves, when handling powders and reloading equipment.
- Avoid inhaling powder dust and ensure proper ventilation in your workspace.
- Do not modify the adapter in any way, as this may compromise safety and performance.
- If you experience any difficulties during installation or use, stop immediately and consult the manufacturer's support.

Instructions for Installation and Usage

1. Installation:

- Ensure that the Frankford Arsenal X10 press is turned off and unplugged.
- Remove any existing powder measure from the press.
- Align the Dillon Powder Measure Adapter with the mounting points on the Frankford Arsenal X10.
- Securely fasten the adapter using the provided screws, ensuring it is tightly fitted.
- Attach the Dillon Powder Measure to the adapter, ensuring it is secure and stable.

2. Usage:

- Before each use, inspect the adapter and powder measure for any signs of wear or damage.
- Set the desired powder charge using the Dillon Powder Measure.
- Perform a test run with a small quantity of powder to ensure proper functioning.
- Always follow safe reloading practices and never leave the equipment unattended while in use.
- After use, clean the equipment thoroughly to prevent powder residue buildup.

Disposal Instructions

- Dispose of any packaging materials in accordance with local waste management regulations.
- If the product becomes damaged or is no longer in use, dispose of it responsibly by following local electronic waste disposal guidelines.

- Do not throw the product into regular household waste.

Contact Information for Further Support

For any questions or concerns regarding the Powder Funnel for Dillon Powder Measure Adapter, please refer to the manufacturer's website or customer support resources. Ensure that you have the product information readily available for assistance.

By following these safety instructions, you can ensure a safe and effective experience with your Powder Funnel for Dillon Powder Measure Adapter. Thank you for your attention to safety!