

DEAD LEVEL SCOPE LEVELING DEVICE - BADGER ORDNANCE DEAD LEVEL SCOPE LEVELING DEVICE

[Gunsmith Tools](#) > [Sight & Scope Installation Tools](#) > [Scope Reticle Levelers](#)

The Dead Level levels your reticle in relation to the Earth taking out any margin of error of the reticle not being perfectly level with the scope body. Simply attach your mounted scope to the Dead Level, level the device with the precision thumbscrews to center up the bulls-eye level, then just level the reticle with a predetermined level line or plumb bob. Aluminum Mil. Spec. Now features an Anodized Hard Coat Type III in a crimson and black finish. Instructions included. FOR USE WITH MIL STD 1913 PICATINNY COMPLIANT RINGS AND MOUNTS



Attributes

- Name: [BADGER ORDNANCE DEAD LEVEL SCOPE LEVELING DEVICE](#)
- Manufacturer: [BADGER ORDNANCE](#)
- Product no.: 093000051
- Mfr. No.: 200-50
- Delivery weight: 0.862kg
- Shipping height: 60mm
- Shipping width: 112mm
- Shipping length: 274mm

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Dead Level Scope Leveling Device Safety Instruction Guide](#)
- [About Us](#)

Dead Level Scope Leveling Device Safety Instruction Guide

Introduction

Thank you for choosing the Dead Level Scope Leveling Device by Badger Ordnance. This guide provides essential safety information and instructions to ensure the safe and effective use of your product. Please read this guide thoroughly before use.

General Safety Guidelines

- Ensure the product is used only for its intended purpose.
- Follow all instructions carefully to avoid potential hazards.
- Regularly inspect the device for any signs of damage or wear before use.
- Keep the product out of reach of children and vulnerable individuals.
- In case of any safety concerns, report them to the appropriate authorities.
- Check for product recall updates on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always ensure that the Dead Level is securely attached to your mounted scope before attempting to level your reticle.
- Use the precision thumbscrews to level the device correctly; improper leveling may lead to inaccurate scope alignment.
- Avoid using the device in extreme weather conditions that may affect its performance.
- Do not modify or alter the Dead Level in any way, as this may compromise its safety features.
- If you experience any issues while using the device, discontinue use immediately and consult a qualified technician.

Instructions for Installation and Usage

1. Preparing for Installation

- Ensure that your firearm is unloaded and pointed in a safe direction.
- Gather all necessary tools for installation, including a compatible mounting system.

2. Attaching the Dead Level

- Attach the Dead Level to your mounted scope using MIL STD 1913 Picatinny compliant rings and mounts.
- Ensure that the device is firmly secured and does not move during use.

3. Leveling the Device

- Use the precision thumbscrews to adjust the level of the Dead Level until the bullseye level is centered.
- Confirm that the device is level before proceeding to adjust the reticle.

4. Leveling the Reticle

- Utilize a predetermined level line or plumb bob to align the reticle accurately.
- Make any necessary adjustments to ensure that the reticle is perfectly level with the scope body.

5. Final Checks

- Doublecheck all adjustments and ensure that the device is securely mounted.
- Perform a final inspection to confirm that there are no loose components.

Disposal Instructions

- Dispose of the Dead Level Scope Leveling Device in accordance with local regulations for electronic waste.
- Ensure that any packaging materials are recycled or disposed of properly.
- Do not dispose of the device in regular household waste.

Contact Information for Further Support

For any inquiries or support regarding the Dead Level Scope Leveling Device, please reach out to your local authorized dealer or manufacturer representative. They will provide assistance based on your specific needs and concerns.

Thank you for your attention to these safety guidelines. Your safety and satisfaction are our top priorities. Enjoy using your Dead Level Scope Leveling Device responsibly.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk