

BORE CLEANING FOAM (AEROSOL)

Gun Cleaning & Chemicals

Preis pro 100ml: 7,45€



Table of Contents

- Startpage
- Safety Instruction Guide for BORE CLEANING FOAM (AEROSOL)
- About Us

Safety Instruction Guide for BORE CLEANING FOAM (AEROSOL)

Introduction

Thank you for choosing BORE CLEANING FOAM (AEROSOL) by GENERAL NANO PROTECTION. This guide provides essential safety instructions to ensure the safe and effective use of this product. Please read this guide carefully before using the product.

General Safety Guidelines

- Ensure that the product is used in a wellventilated area.
- Keep the product out of reach of children and pets.
- Do not use the product near open flames or sources of ignition.
- Avoid contact with eyes and skin. If contact occurs, rinse thoroughly with water.
- Do not ingest. If swallowed, seek medical attention immediately.
- Store the product in a cool, dry place away from direct sunlight.
- Check for any recalls or safety alerts related to the product on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear protective gloves and goggles when using the aerosol.
- Do not spray towards yourself or other individuals.
- Use only as directed on the product label.
- Avoid prolonged inhalation of aerosol mist.
- Do not puncture or incinerate the canister, even when empty.
- If you experience any adverse reactions, discontinue use immediately and consult a physician.

Instructions for Installation and Usage

1. Preparation:

- Shake the canister well before use.
- Ensure the area is wellventilated.

2. Application:

- Hold the canister upright, approximately 1520 cm away from the surface to be cleaned.
- Press the nozzle to release the foam onto the bore of the firearm.
- Allow the foam to sit for the recommended time as indicated on the label.

3. PostApplication:

- Wipe away any excess foam with a clean cloth.
- Ensure the firearm is dry before using it again.

Disposal Instructions

- Do not dispose of the product in household waste.
- Follow local regulations for aerosol disposal.
- If the canister is empty, recycle it according to your local recycling guidelines.
- If the canister is not empty, take it to a designated hazardous waste collection site.

Contact Information for Further Support

For any safety inquiries or further support regarding the use of BORE CLEANING FOAM (AEROSOL), please refer to the product packaging or the manufacturer's website for contact details.

Thank you for your attention to these safety instructions. Your safety is our priority.

About Us

Brownells Austria

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.at