

Digital Powder Scale Set with Trickler - 50 g × 0.001 g

[Gunsmith Tools](#) > [Stock Work & Finishing](#) > [Stock Making Hand Tools](#)

The Prussia Precision Digital Powder Scale Set with Trickler is a high-precision measuring solution designed for reloaders who demand maximum consistency and exact powder charges. With a resolution of 0.001 g and a capacity of 50 g, it provides the accuracy required for fine load development and repeatable results.

Precise powder measurement is one of the most critical factors in reloading, and this scale is built to deliver reliable readings for even the smallest increments. Whether you are developing match-grade ammunition or refining loads for long-range performance, the Prussia Precision scale ensures full control over every charge.

The included powder trickler allows controlled, step-by-step dispensing, making it easy to reach the exact target weight without overshooting. For improved handling and cleaner operation, the dispensing pen is antistatic coated, reducing powder adhesion and ensuring smoother, more consistent trickling during precise charge work.

This combination is ideal for shooters who value precision over speed and want an efficient, professional workflow at the reloading bench.

Compact, accurate, and purpose-built for serious use, the Prussia Precision Digital Powder Scale Set delivers dependable measurement performance for modern reloaders.

NO IMAGE
AVAILABLE

Attributes

- Name: [Digital Powder Scale Set with Trickler - 50 g × 0.001 g](#)
- Manufacturer: [PRUSSIA PRECISION](#)
- Product no.: EU2016256
- Mfr. No.: PP-1564-BLK
- Colour: Black
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm
- UPC: 726529841152

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Prussia Precision Digital Powder Scale Set with Trickler](#)
- [About Us](#)

Safety Instruction Guide for Prussia Precision Digital Powder Scale Set with Trickler

Introduction

Thank you for choosing the Prussia Precision Digital Powder Scale Set with Trickler. This guide provides essential safety information and instructions to ensure the safe and effective use of your scale. Please read this guide carefully before using the product.

General Safety Guidelines

- Always handle the scale with care to prevent damage.
- Keep the scale away from moisture and extreme temperatures.
- Use the scale only for its intended purpose: measuring powder for reloading ammunition.
- Ensure the scale is placed on a stable and flat surface for accurate measurements.
- Keep the scale and all accessories out of reach of children and pets.
- Regularly check for any signs of damage or wear. If any part is damaged, discontinue use immediately.

Specific Safety Precautions for Use

- Avoid overloading the scale beyond its maximum capacity of 50 g.
- Do not attempt to disassemble or modify the scale in any way.
- Use the included powder trickler for controlled dispensing to prevent spills and accidents.
- Ensure that the dispensing pen is clean and free from powder buildup to maintain accuracy.
- Do not use the scale in dusty or dirty environments that may affect its performance.
- If using in combination with other equipment, ensure compatibility to prevent hazards.

Instructions for Installation and Usage

1. Setup:

- Unbox the scale and ensure all components are included: the scale, trickler, and dispensing pen.
- Place the scale on a flat, stable surface, away from direct sunlight and moisture.
- Plug in the scale or insert batteries as per the manufacturer's instructions.

2. Calibration:

- Before first use, calibrate the scale according to the instructions provided in the user manual.
- Use certified calibration weights for accuracy.

3. Using the Scale:

- Turn on the scale and allow it to warm up for a few moments.
- Place the empty container on the scale and tare it to zero.
- Use the powder trickler to dispense powder gradually until the desired weight is reached.
- Always ensure the scale reads zero before adding powder.

4. Maintenance:

- Clean the scale with a soft, dry cloth after each use to prevent powder buildup.
- Store the scale in a dustfree environment when not in use.

Disposal Instructions

- Dispose of the scale and accessories responsibly, following local regulations for electronic waste.
- Remove batteries before disposal and recycle them according to local guidelines.

Contact Information for Further Support

For any safety inquiries or concerns regarding the Prussia Precision Digital Powder Scale Set with Trickler, please reach out to the designated EU contact point provided by the manufacturer.

By following these safety instructions, you can ensure a safe and effective experience with your Prussia Precision Digital Powder Scale Set with Trickler. Thank you for your attention to these important guidelines.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk